

SWITCH MACHINE

10-22-07

GMV01-000-01

Super

SWITCH MACHINE, REV. S, DATED 4-10-06

Sheet 7

GM4000A™ CONFIGURATION KEY FOR MODEL NUMBER

Code	MODEL NUMBER	WM
CONTROL CONFIGURATION		
<u>A</u>	GMV00-000-01	Dual Control (Hand Throw, With Hand Crank Capability)
<u>B</u>	GMV00-000-02	Dual Control (Hand Throw, W/O Hand Crank Capability)
<u>C</u>	GMV00-000-03	Single Control (No Hand Throw, With Hand Crank Capability)
<u>D</u>	GMV00-000-04	Single Control (No Hand Throw, With Hand Crank Capability, No Latch Out)
MACHINE ORIENTATION		
<u>L</u>	Left Hand	
<u>R</u>	Right Hand	
LOCK RODS		
<u>N</u>	GM050-300-01	Narrow Notch Threaded End 3.5 – 6.5 Inch Adjustment
<u>W</u>	GM050-300-02	Wide Notch Threaded End 3.5 – 6.5 Inch Adjustment
<u>S</u>	GM050-300-03	Narrow Notch Spade End 3.5 – 6.5 Inch Adjustment
<u>B</u>	GM050-300-04	Wide Notch Spade End 3.5 – 6.5 Inch Adjustment
<u>C</u>	GM050-300-05	Wide Notch Spade End 4.5 – 6.0 Inch Adjustment
<u>E</u>	GM050-300-07	Narrow Notch Threaded End 3.0 – 6.5 Inch Adjustment
For Lock Rods -01 Thru -07 Add: (4) GMV00-012-00, (2) GMV00-013-00 AND (2) GMV00-014-00		
<u>X</u>	No Lock Rod Add: Only (2) Covers GMV00-011-00	
POINT DETECTOR ROD		
<u>T</u>	GMV00-500-01 Swivel Threaded End With Rivets	
<u>S</u>	GMV00-500-02 Solid Spade End	
<u>P</u>	GMV00-500-03 Swivel Threaded End With Grease Pin	
<u>C</u>	GMV00-500-04 Swivel Threaded End With Grease Pin 4.5-6 inch	
CONTROLLER CONFIGURATION		
<u>S</u>	GMV00-043-00 Standard Controller	
<u>E</u>	GMV00-044-00 Enhanced Controller	
GEAR BOX HEATER		
<u>B</u>	55290-040-00 (24VDC & 110VAC/DC) Gear Box Heater	
<u>N</u>	NO Gear Box Heaters	
CONDENSATION HEATERS		
<u>A</u>	55290-041-00 24 Volt Heater	
<u>B</u>	55290-042-00 110 Volt Heater	
<u>C</u>	Both Heaters	
<u>N</u>	NO Condensation Heater	
LATCH STANDS		
<u>L</u>	GMV00-400-01 (2) Required Per Machine	
<u>N</u>	No Latch Stands	
TOOLS (Optional Accessory)		
<u>B</u>	Hand Crank & Spoon Gauge (.38/.25) & Tool Kit (GMA50-012-00, GMA50-002-00, GMK50-000-01)	
<u>S</u>	GMA50-002-00 Spoon Gauge (.38/.25)	
<u>H</u>	GMA50-012-00 Hand Crank	
<u>E</u>	GMA50-013-00 Hand Crank, Hex End And: 50570-018-00 Ratcheting Crank	
<u>C</u>	GMA50-014-00 Spoon Gauge (6.0/4.5mm)	
<u>K</u>	GMK50-000-01 Maintainer Tool Kit	
<u>N</u>	NO Tools	
HAND THROW LETTER KIT (Optional Accessory)		
<u>K</u>	GMK50-004-01 Letters "N" & "R"	
<u>N</u>	NO Hand Throw Letter Kit	
HARNES ADAPTER OPTION		
<u>A</u>	GMK50-013-01 Kit, Polarized Switch Repeater Harness	
<u>H</u>	GMK50-010-01 Wire Harness Adapter for Motor End Wire Entrance	
<u>N</u>	NO Harness Adapter	
LATCH OUT		
<u>A</u>	No Latch Out	
<u>B</u>	Restorable Latch Out	
<u>C</u>	Restorable Latch Out	
<u>D</u>	Non-Restorable Latch Out (GMA50-107-01)	
ADDITIONAL ACCESSORY TO BE ORDERED SEPARATELY		
	GMA50-100-01	Puller Complete, Bushing

ALSTOM