

# SWITCH MACHINE

12-4-09

Super

SWITCH MACHINE, REV. Z, DATED 4-16-09

Sheet 8 Of 8

## GM4000A™ CONFIGURATION KEY FOR MODEL NUMBER

Code	MODEL NUMBER	WM
<b>CONTROL CONFIGURATION</b>		
A	GMV00-000-01	Dual Control (Hand Throw, With Hand Crank Capability)
B	GMV00-000-02	Dual Control (Hand Throw, W/O Hand Crank Capability)
C	GMV00-000-03	Single Control (No Hand Throw, With Hand Crank Capability)
D	GMV00-000-04	Single Control (No Hand Throw, With Hand Crank Capability, No Latch Out)
<b>MACHINE ORIENTATION</b>		
L	Left Hand	
R	Right Hand	
<b>LOCK RODS</b>		
N	GM050-300-01	Narrow Notch Threaded End 3.5 – 6.5 Inch Adjustment
W	GM050-300-02	Wide Notch Threaded End 3.5 – 6.5 Inch Adjustment
S	GM050-300-03	Narrow Notch Spade End 3.5 – 6.5 Inch Adjustment
B	GM050-300-04	Wide Notch Spade End 3.5 – 6.5 Inch Adjustment
C	GM050-300-05	Wide Notch Spade End 4.5 – 6.0 Inch Adjustment
E	GM050-300-07	Narrow Notch Threaded End 3.0 – 6.5 Inch Adjustment
For Lock Rods –01 Thru –07 Add: (4) GMV00-012-00, (2) GMV00-013-00, (2) GMV00-014-00		
X	No Lock Rod Add: Only (2) Covers GMV00-011-00	
<b>POINT DETECTOR ROD</b>		
T	GMV00-500-01	Swivel Threaded End With Rivets
S	GMV00-500-02	Solid Spade End
P	GMV00-500-03	Swivel Threaded End With Grease Pin
C	GMV00-500-04	Swivel Threaded End With Grease Pin 4.5-6 inch
D	GMV00-500-05	Threaded End Non Swivel
<b>CONTROLLER CONFIGURATION</b>		
S	GMV00-043-00	Standard Controller
E	GMV00-044-00	Enhanced Controller
<b>GEAR BOX HEATER</b>		
B	55290-040-00	(24VDC & 110VAC/DC) Gear Box Heater
N	NO Gear Box Heaters	
<b>CONDENSATION HEATERS</b>		
A	55290-041-00	24 Volt Heater
B	55290-042-00	110 Volt Heater
C	Both Heaters	
N	NO Condensation Heater	
<b>LATCH STANDS</b>		
L	GMV00-400-01 (2) Required Per Machine	
N	No Latch Stands	
<b>TOOLS (Optional Accessory)</b>		
B	Hand Crank & Spoon Gauge (.38/.25) & Tool Kit (GMA50-012-00, GMA50-002-00, GMK50-000-01)	
S	GMA50-002-00 Spoon Gauge (.38/.25)	
H	GMA50-012-00 Hand Crank	
E	GMA50-013-00 Hand Crank, Hex End And: 50570-018-00 Ratcheting Crank	
C	GMA50-014-00 Spoon Gauge (6.0/4.5mm)	
K	GMK50-000-01 Maintainer Tool Kit	
N	NO Tools	
<b>HAND THROW LETTER KIT (Optional Accessory)</b>		
K	GMK50-004-01 Letters "N" & "R"	
N	NO Hand Throw Letter Kit	
<b>HARNESS ADAPTER OPTION</b>		
A	GMK50-013-01 Kit, Polarized Switch Repeater Harness	
H	GMK50-010-01 Wire Harness Adapter for Motor End Wire Entrance	
N	NO Harness Adapter	
<b>LATCH OUT</b>		
A	No Latch Out	
B	Restorable Latch Out	
C	Restorable Latch Out	
D	Non-Restorable Latch Out (GMA50-107-01)	
E	Non-Restorable Latch Out, Mechanical (GMK50-020-01)	
<b>ADDITIONAL ACCESSORY TO BE ORDERED SEPARATELY</b>		
GMA50-100-01	Puller Complete, Bushing	
GMA50-105-01	Cam Bar Detection Switch Kit (For switch machines manufactured with PD Switch Module (GM050-800-02) Rev.'s A, B & C, AND Configured with non-restorable latch out)	
GMA50-107-01	Cam Bar Detection Switch Kit (For switch machines manufactured with PD Switch Module (GM050-800-02) Rev. D and later, AND Configured with non-restorable latch out)	
GMA50-108-00	Hand Crank Lock	
GMA50-109-01	Hand Crank, Torque Limiting	

ALSTOM